



Movement that inspires

Campanie rechemare service

Model: SORENTO XM

Intervenție: Înlocuire furtun alimentare
carburant

VIN	Număr campanie
KNAKU814CC5240209	171072
KNAKU814CC5246676	171072
KNAKU814CC5250438	171072
KNAKU814DC5246678	171072
KNAKU814DC5246679	171072
KNAKU814DC5246680	171072
KNAKU814DC5246681	171072
KNAKU814DC5246764	171072
KNAKU814DC5246765	171072
KNAKU814DC5246768	171072
KNAKU814DC5250024	171072
KNAKU814DC5250541	171072